

2 OF 83



210-344-1344 S.A.
713-923-2133 Houston
512-804-2637 Austin
888-390-5692 Toll Free
mgessner@amerispec.net
www.amerispec.net/gessner

PROPERTY INSPECTION REPORT

Prepared For: Tony Scarnato
(Name of Client)

Concerning: 2623 Villa Norte San Antonio, TX 78228
(Address or Other Identification of Inspected Property)

By: Gary Armstrong 9604 08/23/07
(Name and License Number of Inspector) (Date)

(Name, License Number and Signature of Sponsoring Inspector, if required)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Number: 20070839613 Phone Number: _____

Date of Inspection: 08/23/07 Fax Number: _____

Time of Inspection: 4:30pm

Client Mailing Address: _____

City/State/Zip: _____

SPECIAL NOTES:

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair
I	NI	NP	R	Inspection Item	

I. STRUCTURAL SYSTEMS

A. Foundations (If all crawl space areas are not inspected, provide an explanation.)
Comments (An opinion on performance is mandatory.):

FOUNDATION TYPE- Concrete slab on grade.
 CONCRETE FOUNDATION OBSERVATIONS- Foundation appears to be functioning normally at time of inspection.
 Minor signs of past settlement observed in the form of hair line type cracking to finished surfaces at front porch, at garage floor.

B. Grading and Drainage
Comments
 Structure is built on a slightly sloped lot. Grade at foundation appears inadequate at right side, at rear right of a/c unit, at left of house areas. Repair drainage at these areas to properly drain away from foundation, to prevent water accumulation and possible stress to structure.

C. Roof Covering (If the roof is inaccessible, report the method used to inspect.)
Comments
 METHOD USED TO INSPECT ROOF- The following was observed upon walking on the roof.
 DESCRIPTION OF MATERIALS- Composition and/or fiberglass shingles. Note: Average life expectancy under normal installation/conditions is between 10 -14 years. Approximate age of roof. Approximate age of this roof covering is believed to be between 5 and 10 years old.
 ROOF COVERING OBSERVATIONS- Starter strip around perimeter edge of roof improperly installed, not sealed down as per manufacturer installation instructions. Seal all exposed fasteners at ridge caps, flashings on roof.

D. Roof Structure and Attic (If the attic is inaccessible, report the method used to inspect.)
Comments
 ACCESS METHOD/LIMITATIONS- Full access
 ATTIC OBSERVATIONS- Truss framing
 ROOF STRUCTURE OBSERVATIONS- No problems observed during this inspection period.
 INSULATION OBSERVATIONS- A combination of fiberglass (and/or rock wool) batt type and blown in insulation were present.
 The insulation layer is approximately, 7 - 10 inches thick.

E. Walls (Interior and Exterior)
Comments

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

INTERIOR WALL OBSERVATIONS- INTERIOR WALLS ARE COVERED WITH THE FOLLOWING MATERIAL(S)- Drywall.
 OBSERVATIONS- holes in wall at right front bedroom
 Stored items or furnishings prevent full inspection.

EXTERIOR WALL OBSERVATIONS- EXTERIOR WALLS ARE CONSTRUCTED OF THE FOLLOWING MATERIALS- Aluminum/vinyl siding. Brick and/or block (stone) veneer over wood framing.
 Cement Fiber type siding. Soffit(s), eave(s), and/or trim are painted wood.
 OBSERVATIONS-gaps in soffit at left corner garage
 Exposed nails at 1x2 trim left, right sides.
 Deteriorated wood trim at right front corner, at garage door trim. Replace all deteriorated wood.
 Reseal gaps at lap siding left, rear, right walls.
 Seal holes in trim at rear left, at rear hose bibb

F. Ceilings and Floors
Comments

CEILING COVERING(S)- CEILING OBSERVATIONS- nail pops on ceiling at kitchen.
 FLOOR COVERING(S)-loose carpet observed throughout

G. Doors (Interior and Exterior)
Comments

INTERIOR DOOR OBSERVATIONS-holes in door at right front bedroom.
 EXTERIOR DOOR OBSERVATIONS- missing interior trim at side door to exterior.
 Signs of leakage to interior

H. Windows
Comments

OBSERVATIONS- No problems observed during this inspection period.
 Note: exterior of windows must be kept sealed to prevent leakage.

I. Fireplace/Chimney
Comments
 Not Present

J. Porches, Decks and Carports (Attached)
Comments

PORCH OBSERVATIONS- No problems observed during inspection period.

K. Other
Comments

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

Not Present

II. ELECTRICAL SYSTEMS

A. Service Entrance and Panels
Comments:
 SERVICE COMMENTS: Under Ground
 MAIN PANEL COMMENTS: LOCATION- Exterior of house at right of house
 PREDOMINANT OVERLOAD PROTECTION DEVICES- Circuit breakers are provided.
 MAIN ELECTRICAL PANEL OBSERVATIONS-white wiring used at hot circuit, not properly marked in panel.

SUB-PANEL COMMENTS: LOCATION- Garage
 SUB-ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

B. Branch Circuits - Connected Devices and Fixtures (Report as in need of repair the lack of ground fault circuit protection where required.)
Comments:
 FEEDERS- Copper, Aluminum (220 volt OK)
 VISIBLE BRANCH WIRING TYPE- Grounded type branch wiring present. Copper
 BRANCH WIRING OBSERVATIONS-loose ceiling fan at master bedroom.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

A. Heating Equipment #1:
Type/Energy Source: System Type- Electric Forced Air Heat Pump.
Comments:
 Unit located at hall closet.
 Heating System- The heating system operated correctly at the time of the inspection.

B. Cooling Equipment #1:
Type/Energy Source: Electric.
Comments:
 Cooling System- - Central, - Split System.
 Trane est 2 1/2 ton 2000 unit located at exterior.
 AIR TEMPERATURE DIFFERENTIAL- Temperature drop/differential observed between 15 - 20 degrees. (taken between interior return and supply air) This is considered a normal operating range.
 EVAPORATOR OBSERVATIONS-interior blower and coils in need of cleaning/servicing.
 Debris and fungal type growth observed at interior blower unit in need of proper removal.
 CONDENSER (EXTERIOR UNIT) OBSERVATIONS-exterior coils in need of cleaning/servicing.

I=Inspected NI=Not Inspected NP=Not Present R=Not Functioning or in Need of Repair

I	NI	NP	R	Inspection Item
---	----	----	---	-----------------

Replace insulation on exterior refrigerant piping to unit

C. Ducts and Vents

Comments:

DUCTWORK TYPE- Fiberglass duct board and/or flexible type ducts were primarily used for distribution/return system throughout.

Ductwork, Air Chase and/or Plenum Observations-all duct joints in need of sealing to prevent leakage

It is not recommended to install cord or outlet for water heater in return chase.

FILTER OBSERVATIONS- Filters are very dirty.

IV. PLUMBING SYSTEM

A. Water Supply System and Fixtures

Comments:

The potable water supply source is- Municipal service is primary water source.

SUPPLY PIPING TYPE- Copper, Galvanized

POTABLE WATER LINE OBSERVATIONS- water pressure to house slightly excessive at 90 psi at time of inspection. Recommend plumber for repairs to 80 psi or less

Bathroom #1 MASTER BATHROOM:

LAVATORY- No problems observed during this inspection period.

TOILET/BIDET PLUMBING- No problems observed during this inspection period.

TUB/SHOWER PLUMBING- missing stopper at tub.

B. Drains, Wastes, Vents

Comments:

DRAIN/WASTE & VENT PIPING TYPE- PVC plastic

SEWER PIPE OBSERVATIONS- No problems observed during this inspection period.

Bathroom #1 MASTER BATHROOM:

LAVATORY- No problems observed during this inspection period.

TOILET/BIDET PLUMBING- No problems observed during this inspection period.

TUB/SHOWER PLUMBING- No problems observed during this inspection period.

C. Water Heating Equipment #1: (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)

Energy Source: Electrically operated.

Comments:

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

State 40 gallon 2001 unit located at hall closet.
 No problems observed during this inspection period.

- D. **Hydro Therapy Equipment**
Comments:
Not Present

V. APPLIANCES

- A. **Dishwasher**
Comments:
 No problems observed during limited test run of appliance.

- B. **Food Waste Disposer**
Comments:
Deficiencies- Noise and or vibration was present when operated.

- C. **Range Hood**
Comments:
 No problems observed during limited test run of appliance.

- D. **Ranges/Ovens/Cooktops**
Comments:
 oven not operated, in use at time of inspection

- E. **Microwave Cooking Equipment**
Comments:
Not Present

- F. **Trash Compactor**
Comments:
Not Present

- G. **Bathroom Exhaust Fans and/or Heaters**
Comments:
 Bath vent humms only, not functional

- H. **Whole House Vacuum Systems**
Comments:
Not Present

- I. **Garage Door Operators**
Comments:

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

door out of track, in need of repair

J. **Door Bell and Chimes**
Comments:
 No problems observed.

K. **Dryer Vents**
Comments:
Vent cap is damaged.

L. **Other Built-in Appliances**
Comments:
 Not Present

VI. OPTIONAL SYSTEMS

A. **Lawn Sprinklers**
Comments:
 Not Present

B. **Swimming Pools and Equipment**
Comments:
 Not Present

C. **Outbuildings**
Comments:
 Not Present

D. **Outdoor Cooking Equipment**
Energy Source:
Comments:
 Not Present

E. **Gas Lines**
Comments:
 Not Present

F. **Water Wells** (A coliform analysis is recommended.)
Type of Pump:
Type of Storage Equipment:
Comments:

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item
I	NI	NP	R					

G. Septic Systems
Comments:

Not Present

Not Present

H. Security Systems
Comments:

security testing is not part of this inspection

I. Fire Protection Equipment
Comments:

Not Present