



818 S. FLORES ST. ① SAN ANTONIO, TEXAS 78204 ① www.saha.org

Procurement Department

## **ADDENDUM #2**

**To: RFQ# 1104-909-62-3479**  
**RFQ for Exterior Building Repairs for Guadalupe Subdivision**  
**Date: May 5, 2011**

---

**Question 1: Do we use exterior material or do we use cement board material (hardi-board)? (1x4's and plywood area)**

**Answer 1: Material is to match existing material.**

**Question 2: What is holding the porch? 4x4? If these material are deteriorate, is this a change order or do we estimate in replacing the support?**

**Answer 2: Contractor shall inform the Maintenance Supervisor if any deteriorated material is discovered. No post will be replaced.**

**Question 3: Are you supplying the paint or do we provide the paint to repaint?**

**Answer 3: As stated in the RFQ, the Contractor shall supply all material.**

**Question 4: Do the columns at the rear of these houses included?**

**Answer 4: Yes the rear columns are included.**

**Question 5: The 4x4 at some of these columns, do we replace with weather treated lumber or cedar?**

**Answer 5: No posts will be replaced.**

**Question 6: Is there a cost estimate for this project?**

**Answer 6: All Small Purchase Threshold (SAHA's RFQ) must by State law be less than \$50,000.00.**

**By: Carl Bottoms**  
**Procurement Supervisor**

**Date: May 5, 2011**