

PROPERTY INSPECTION REPORT

Prepared For: SAHA

(Name of Client)

Concerning: 615 Matthews San Antonio, TX 78237

(Address or Other Identification of Inspected Property)

By: Jon Krauss 4255 02/15/08

(Name and License Number of Inspector) (Date)

(Name, License Number and Signature of Sponsoring Inspector, if required)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Number: 20080241836 Phone Number: _____
Date of Inspection: 02/15/08 Fax Number: _____
Time of Inspection: _____
Client Mailing Address: _____
City/State/Zip: _____

SPECIAL NOTES:

Report Identification 615 Matthews

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

I=Inspected				NI=Not Inspected	NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R				

I. STRUCTURAL SYSTEMS

A. Foundations (If all crawl space areas are not inspected, provide an explanation.)
Comments (An opinion on performance is mandatory):
 FOUNDATION TYPE- Concrete slab on grade.
 CONCRETE FOUNDATION OBSERVATIONS- Foundation appears to be functioning normally at time of inspection.
 Minor signs of past settlement observed in the form of hair line type cracking to finished surfaces.

B. Grading and Drainage
Comments
 Structure is built on a slightly sloped lot. Grade at foundation appears inadequate at front left of house. Repair drainage at these areas to properly drain away from foundation, to prevent water accumulation and possible stress to structure.

C. Roof Covering (If the roof is inaccessible, report the method used to inspect.)
Comments
 METHOD USED TO INSPECT ROOF- The following was observed upon walking on the roof.
 DESCRIPTION OF MATERIALS- Composition and/or fiberglass shingles. Note: Average life expectancy under normal installation/conditions is between 10 -14 years.
 ROOF COVERING OBSERVATIONS-missing/damaged shingles at right center roof
 Seal all exposed fasteners at ridge caps, flashings on roof.
 Starter strip around perimeter edge of roof improperly installed, not sealed down.

D. Roof Structure and Attic (If the attic is inaccessible, report the method used to inspect.)
Comments
 ACCESS METHOD/LIMITATIONS- Full access
 ATTIC OBSERVATIONS- Truss framing
 ROOF STRUCTURE OBSERVATIONS- No problems observed during this inspection period.
 INSULATION OBSERVATIONS- Blown type insulation (either fiberglass or rock wool) present. The insulation layer is approximately, 6 to 7 inches thick.
 Add throughout for R30 value.

E. Walls (Interior and Exterior)
Comments
 INTERIOR WALL OBSERVATIONS- INTERIOR WALLS ARE COVERED WITH THE FOLLOWING MATERIAL(S)- Drywall.

I=Inspected NI=Not Inspected NP=Not Present R=Not Functioning or in Need of Repair

I	NI	NP	R	Inspection Item
---	----	----	---	-----------------

EXTERIOR WALL OBSERVATIONS- EXTERIOR WALLS ARE CONSTRUCTED OF THE FOLLOWING MATERIALS-

Aluminum/vinyl siding. Soffit(s), eave(s), and/or trim are painted wood. Cement Fiber type siding.

OBSERVATIONS-paint, seal base of wood trim at corners, around house.

Seal joints at eaves at left rear.

F. Ceilings and Floors
Comments

CEILING COVERING(S)- CEILING OBSERVATIONS- No problems observed during this inspection period.

G. Doors (Interior and Exterior)
Comments

INTERIOR DOOR OBSERVATIONS- damaged, delaminated door at master bedroom and sticking in frame.

EXTERIOR DOOR OBSERVATIONS- Moisture related deterioration is present in door(s) and/or related trim in the following area(s). ---breakfast exterior door . Repair damage, reseal exterior and consider cover to protect from elements.

H. Windows
Comments

OBSERVATIONS-swelling, water damage observed at windows at breakfast raea, at rear bedroom

Missing screens one at right window

Cracked glass at rear bedroom.

No flashing observed at rear window

note: windows changed to single pane 3 at breakfast, one master

I. Fireplace/Chimney
Comments

Not Present

J. Porches, Decks and Carports (Attached)
Comments

PORCH OBSERVATIONS- No problems observed during inspection period.

K. Other
Comments

Not Present

I=Inspected NI=Not Inspected NP=Not Present R=Not Functioning or in Need of Repair

I	NI	NP	R	Inspection Item
---	----	----	---	-----------------

II. ELECTRICAL SYSTEMS

- A. Service Entrance and Panels**

Comments:

SERVICE COMMENTS: Under Ground

MAIN PANEL COMMENTS: LOCATION- Exterior of house

PREDOMINANT OVERLOAD PROTECTION DEVICES- Circuit breakers are provided.

MAIN ELECTRICAL PANEL OBSERVATIONS-white wires used as hot legs in panel but not properly marked as hot legs.

SUB-PANEL COMMENTS: LOCATION- Garage

SUB-ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

- B. Branch Circuits - Connected Devices and Fixtures** (Report as in need of repair the lack of ground fault circuit protection where required.):

Comments:

FEEDERS- Copper, Aluminum (220 volt OK)

VISIBLE BRANCH WIRING TYPE- Grounded type branch wiring present. Copper

BRANCH WIRING OBSERVATIONS- WIRING DEFICIENCIES-exposed romex in need of conduit at left exterior two locations.

LIGHTING & CEILING FAN DEFICIENCIES- missing cover on light at left exterior.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

- A. Heating Equipment #1:**
Type/Energy Source: System Type- Electric Forced Air Heat Pump.

Comments:

Unit is located in, closet

Heating System- The heating system operated correctly at the time of the inspection.

- B. Cooling Equipment #1:**
Type/Energy Source: Electric.

Comments:

Est. Size: 2 1/2 ton

Cooling System- - Central, - Split System.

AIR TEMPERATURE DIFFERENTIAL- Temperature drop/differential observed between 15 - 20 degrees. (taken between interior return and supply air) This is considered a normal operating range.

EVAPORATOR OBSERVATIONS-debris observed at interior coils in need of servicing. Gaps in insulation in attic, in need of repairs.

- C. Ducts and Vents**

Comments:

I=Inspected	NI=Not Inspected	NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R	

DUCTWORK TYPE- Fiberglass duct board and/or flexible type ducts were primarily used for distribution/return system throughout.
 Ductwork, Air Chase and/or Plenum Observations-seal all duct connections throughout attic
 Clean loose debris out of return chase.

IV. PLUMBING SYSTEM

A. Water Supply System and Fixtures
Comments:

The potable water supply source is- Municipal service is primary water source.
 SUPPLY PIPING TYPE- Copper
 POTABLE WATER LINE OBSERVATIONS- Appears serviceable.

Bathroom #1 MASTER BATHROOM:

LAVATORY-missing stopper at sink
 TOILET PLUMBING-tank loose, in need of repair
 TUB/SHOWER PLUMBING-water damage at wall outside of tub

Bathroom #2 HALL BATHROOM:

LAVATORY- missing stopper at sink unit
 TOILET PLUMBING- Water closet fill valve leaking in tank when flushed. Repair/replace valve
 TUB/SHOWER PLUMBING- No problems observed during this inspection period.

B. Drains, Wastes, Vents
Comments:

DRAIN/WASTE & VENT PIPING TYPE- PVC plastic
 SEWER PIPE OBSERVATIONS- No problems observed during this inspection period.

Bathroom #1 MASTER BATHROOM:

Bathroom #2 HALL BATHROOM:

C. Water Heating Equipment #1: (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)
Energy Source: Electrically operated.
Comments:

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair	
I	NI	NP	R	Inspection Item			

Location/Coverage: Closet, Hallway.

State 40 gallon 2001 unit;
No problems observed during this inspection period.

- D. Hydro Therapy Equipment**
Comments:
Not Present

V. APPLIANCES

- A. Dishwasher**
Comments:
 Discharge hose is, installed without an air gap. The drain line should be raised to the underside of the counter top.

- B. Food Waste Disposer**
Comments:
 No problems observed during limited test run of appliance.

- C. Range Hood**
Comments:
 No problems observed during limited test run of appliance.

- D. Ranges/Ovens/Cooktops**
Comments:
 Oven present, Electric. No problems observed during this inspection period with operation of unit
 Free standing range is not properly secured in place to prevent accidental tip over. Unit should be secured with wall or floor brackets as a safety precaution.

- E. Microwave Cooking Equipment**
Comments:
Not Present

- F. Trash Compactor**
Comments:
Not Present

- G. Bathroom Exhaust Fans and/or Heaters**
Comments:
 Vent unit present. No problems observed during limited test run of appliance.

I=Inspected				NI=Not Inspected				NP=Not Present				R=Not Functioning or in Need of Repair			
I	NI	NP	R	Inspection Item											

H. Whole House Vacuum Systems
Comments:
Not Present

I. Garage Door Operators
Comments:
Not Present

J. Door Bell and Chimes
Comments:
 No problems observed.

K. Dryer Vents
Comments:
 No problems noted.

L. Other Built-in Appliances
Comments:
Not Present

VI. OPTIONAL SYSTEMS

A. Lawn Sprinklers
Comments:
Not Present

B. Swimming Pools and Equipment
Comments:
Not Present

C. Outbuildings
Comments:
Not Present

D. Outdoor Cooking Equipment
Energy Source:
Comments:
Not Present

E. Gas Lines
Comments:

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item
I	NI	NP	R					

Not Present

F. Water Wells (A coliform analysis is recommended.)
Type of Pump:
Type of Storage Equipment:
Comments:

Not Present

G. Septic Systems
Comments:

Not Present

H. Security Systems
Comments:
 security testing is not part of this inspection

I. Fire Protection Equipment
Comments:

Not Present