



818 S. FLORES ST.

SAN ANTONIO, TEXAS 78204

www.saha.org

Procurement Department

## **ADDENDUM #2**

**To: 1003-909-62-3163**

**RFQ for Repairs at 11206 Prairie Springs**

**Date: April 16, 2010**

---

**NOTE: Contractor must prime all interior walls prior to painting to cover existing brightly colored paint. Contractor must prime all exterior fascia boards and trim prior to painting.**

**Question 1: How many GFCIs, wall plates, switches, covers, and phone jacks need to be replaced?**

**Answer 1: The list below details the quantity of requested items.**

**(1)- GFCI**

**(16) Single pole Switches & (16) Switch cover plates**

**(2) dual single pole switches & (2) dual switch with single switch cover plates**

**(2) dual switch cover plates**

**(1) 220 receptacle cover plate**

**(1) blank cover plate**

**(4) phone jacks**

**(2) cable jacks**

**(28) Receptacles**

**(26) receptacle cover plates**

**(2) exterior weather proof cover plates**

**Question 2: Will new counters you are providing have a backsplash? If so, will the electrical duplex outlet currently located in the backsplash to the right of the sink be cut out by the supplier or will we be required to cut the backsplash to fit in the duplex outlet? Another option is to face the outlet toward the dining room in the drywall under the pass-thru counter. And yet another option is to abandon the outlet.**

**Answer 2: The new countertop will have a backsplash. The contractor will be required to cut the opening for the duplex electrical outlet. The outlet will remain in the current position.**



818 S. FLORES ST. ① SAN ANTONIO, TEXAS 78204 ① [www.saha.org](http://www.saha.org)

---

**Question 3: The storage building in the back yard is scheduled to be removed. It sits on a concrete slab. Do we include removal of the concrete slab?**

**Answer 3: No, leave the concrete slab in place.**

By: Charles R Bode  
Charles Bode, Asst. Director of Procurement

Date: April 16, 2010