



818 S. FLORES ST. SAN ANTONIO, TEXAS 78204 www.saha.org

Procurement Department

ADDENDUM #1

To: 1005-925-42-3221

RFQ: Foundation Repair at Castle Point

Date: June 28, 2010

Question 1: Has there been previous foundation repair to this building?

Answer 1: There are no records of previous foundation repairs.

Question 2: How far do the piers need to be driven?

Answer 2: As stated in the RFQ, "Continuously drive steel piers with a minimum installation force of 50,000 lbs of pressure, to refusal and final point bearing."

By: Carl Bottoms
Procurement Supervisor

Date: June 28, 2010