



818 S. FLORES ST. ① SAN ANTONIO, TEXAS 78204 ① www.saha.org

Procurement Department

ADDENDUM #2

To: 1104-909-62-3481
RFQ for Replace and Paint the Fascia at South San
Date: May 17, 2011

Question 1: We are concerned about the metal edge beening damaged as we try to remove the 2" X 6" fascia. This metal flashing covers just about half of the fascia and will have to be lifted and that's when the damage might happen.

Answer 1: As stated in Section 15.6, the rain edge is to be replaced as required. If it is damaged it shall be replaced.

By: Carl Bottoms
Procurement Supervisor

Date: May 17, 2011