



## ADDENDUM #1

**To: RFQ # 1104-913-47-3470**

**For: Concrete Sidewalk Removal, Replacement & other Concrete work at Lincoln**

**Date: July 27, 2011**

---

Question 1: The dumpster area at bldg. 46 is just a partial r&r of that pad, is that correct?

Answer 1: Yes it is correct

Question 2: 1146 Lombrano and bldg 52 are not the same location. Is this two different locations of work or is it a typo?

Answer 2: They are two different locations. It must be a typo

Question 3: The sidewalk r&r @ bldg 52 is more like 15X4 instead of 5x4 should we make that adjustment?

Answer 3: Yes please make the adjustment.

Question 4: Are we just to reset only the missing or displaced cinder blocks in the dumpster area, or we to rebuild the wall? Also there is no paint, correct?

Answer 4: The whole wall needs to be rebuilt.

**By: Carl Bottoms**

Carl Bottoms, Procurement Supervisor

Date: July 28, 2011