



818 S. FLORES ST. ① SAN ANTONIO, TEXAS 78204 ① www.saha.org

Procurement Department

ADDENDUM #2

To: File 1104-936-37-3454
RFQ for Gate Repair at Alazan
Date: May 3, 2011

Question 1: Are gates wrought iron?

Answer 1: Yes

Question 2: Are the pickets coming off and require re-welding?

Answer 2: No pickets will be removed

Question 3: Is there any concrete work required to reinforce anything?

Answer 3: As stated in addendum 1, Repair or replace concrete footings where leaning or unsecured footing is causing the gates not to latch or align properly

By: Carl Bottoms
Procurement Supervisor

Date: May 3, 2011