



Aladdin Environmental LLC

321 W. Josephine * San Antonio, TX 78212 * 210-736-1826x218 * Fax 210-732-3667
John Spalten – Texas Mold Assessment Consultant MAC0383

October 28, 2008

San Antonio Housing Authority
Attn: Edward Pape, Mirasol Project Manager
459 Precious Street
San Antonio, TX 78237

Re: 139 Villa Arboles, San Antonio, TX

Dear Mr. Pape:

Aladdin Environmental is pleased to submit this limited environmental evaluation on the above residence located at 139 Villa Arboles, San Antonio, TX. This limited evaluation was performed on October 24th, 2008. We have observed the standard of care generally exercised by the profession under similar circumstances and conditions to complete this report.

Mold spores are common in indoor environments. It is not the presence of molds in indoor air that is cause for concern. However, the amplification and dissemination of fungal spores in elevated levels can decrease indoor air quality and lead to adverse health effects.

On the following page, are the samples taken along with any observations and/or suggestions. Based on observations there was no evidence of microbial growth in the house. The lab results indicate the air samples are within acceptable guidelines. The actual lab report is included as well.

The indoor air quality evaluation observations and testing results detailed in this report are for a single sampling episode. Any changes in ambient conditions may have an effect on future conditions. Moisture control is the key to mold control. We reserve the right to amend or modify our stated opinions and conclusion if additional discovery material is provided or otherwise obtained.

We appreciate the opportunity to perform this service for you. Please contact me if you have any further questions.

Sincerely,

John Spalten
MAC0383

Enc: Lab Report

Analyses of the laboratory samples taken along with observations and/or suggestions are as follows:

Air Samples

A1 – Outside

- Sample taken outside for comparison.

A2 – Kitchen/Living

- Lab results show counts of various types of mold, all lower than the outside counts, or within a reasonable variance, with the exception of *Bipolaris*. The overall count is much lower than the outside count.

A3 – Hall @ Bedrooms

- Lab results show counts of various types of mold, all lower than the outside counts, or within a reasonable variance. The overall count is much lower than the outside count.

General Recommendations and/or Observations

- Inspected areas throughout the house. The house was vacant. The house had remodeling recently completed.
- Walls were checked around plumbing fixtures, windows and other possible moisture sources using a moisture meter and all readings were normal.
- Some walls were open for what appeared to be checking on foundation issues.
- Kitchen – All appeared to be in good condition.
- Living – All appeared to be in good condition.
- Bedrooms – All appeared to be in good condition.
- Master Bedroom – All appeared to be in good condition.
- Bathrooms – All appeared to be in good condition.



Kitchen



Hall bath



Master Bath