

6 OF 83



210-344-1344 S.A.  
713-923-2133 Houston  
512-804-2637 Austin  
888-390-5692 Toll Free  
mgessner@amerispec.net  
www.amerispec.net/gessner

### PROPERTY INSPECTION REPORT

**Prepared For:** Tony Scarnato  
(Name of Client)

**Concerning:** 1619 NW 26th San Antonio, TX 78237  
(Address or Other Identification of Inspected Property)

**By:** Gary Armstrong 9604 08/24/07  
(Name and License Number of Inspector) (Date)

\_\_\_\_\_  
(Name, License Number and Signature of Sponsoring Inspector, if required)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

#### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Number: 20070939636 Phone Number: \_\_\_\_\_

Date of Inspection: 08/24/07 Fax Number: \_\_\_\_\_

Time of Inspection: 9:00am

Client Mailing Address: \_\_\_\_\_

City/State/Zip: \_\_\_\_\_

#### SPECIAL NOTES:

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item
I	NI	NP	R					

**I. STRUCTURAL SYSTEMS**

**A. Foundations** (If all crawl space areas are not inspected, provide an explanation.)  
*Comments* (An opinion on performance is mandatory.):  
 FOUNDATION TYPE- Concrete slab on grade.  
 CONCRETE FOUNDATION OBSERVATIONS- Foundation appears to be functioning normally at time of inspection.  
 Minor signs of past settlement observed in the form of hair line type cracking to finished surfaces at garage floor areas.

**B. Grading and Drainage**  
*Comments*  
 Structure is built on a slightly sloped lot. Grade at foundation appears inadequate at right rear, at rear a/c unit, at front porch area, at front yard areas. . Repair drainage at these areas to properly drain away from foundation, to prevent water accumulation and possible stress to structure.

**C. Roof Covering** (If the roof is inaccessible, report the method used to inspect.)  
*Comments*  
 METHOD USED TO INSPECT ROOF- The following was observed upon walking on the roof.  
 DESCRIPTION OF MATERIALS- Composition and/or fiberglass shingles. Note: Average life expectancy under normal installation/conditions is between 10 -14 years. Approximate age of roof. Approximate age of this roof covering is believed to be between 5 and 10 years old.  
 ROOF COVERING OBSERVATIONS- Seal all exposed fasteners at ridge caps, flashings on roof.  
 Starter strip around perimeter edge of roof improperly installed, not sealed down as per manufacturer installation instructions.  
 Roof covering observed showing normal wear for age.

GUTTERING OBSERVATIONS- DAMAGE/DEFECTS NOTED- add downspout at front of house gutter to control drainage.

**D. Roof Structure and Attic** (If the attic is inaccessible, report the method used to inspect.)  
*Comments*  
 ACCESS METHOD/LIMITATIONS- Full access  
 ATTIC OBSERVATIONS- Truss framing.  
 ROOF STRUCTURE OBSERVATIONS- No problems observed during this inspection period.

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item
I	NI	NP	R					

INSULATION OBSERVATIONS- Blown type insulation (either fiberglass or rock wool) present. **The insulation layer is approximately, 7 to 9 inches thick.**

- 

**E. Walls (Interior and Exterior)**  
*Comments*

INTERIOR WALL OBSERVATIONS- INTERIOR WALLS ARE COVERED WITH THE FOLLOWING MATERIAL(S)- Drywall.

OBSERVATIONS- No problems observed during this inspection period.  
Stored items or furnishings prevent full inspection.

EXTERIOR WALL OBSERVATIONS- EXTERIOR WALLS ARE CONSTRUCTED OF THE FOLLOWING MATERIALS- Brick and/or block (stone) veneer over wood framing.

Cement Fiber type siding. Soffit(s), eave(s), and/or trim are painted wood

OBSERVATIONS- seal lap siding joints at sides, at rear  
Deteriorated wood at base of post at front porch.

Exposed nails, loose at garage door trim

**Trim base of jambs at garage overhead door**

- 

**F. Ceilings and Floors**  
*Comments*

CEILING COVERING(S)- CEILING OBSERVATIONS- No problems observed during this inspection period.

- 

**G. Doors (Interior and Exterior)**  
*Comments*

INTERIOR DOOR OBSERVATIONS- No problems observed during this inspection period.

EXTERIOR DOOR OBSERVATIONS- Moisture related deterioration is present in door(s) and/or related trim in the following area(s). ---side garage door . Repair damage, reseal exterior and consider cover to protect from elements.

- 

**H. Windows**  
*Comments*

OBSERVATIONS- No problems observed during this inspection period.

- 

**I. Fireplace/Chimney**  
*Comments*

Not Present

- 

**J. Porches, Decks and Carports (Attached)**  
*Comments*

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair	
I	NI	NP	R	Inspection Item			

PORCH OBSERVATIONS- No problems observed during inspection period.

- K. Other  
 Comments  
 Not Present

**II. ELECTRICAL SYSTEMS**

- A. Service Entrance and Panels  
 Comments:

SERVICE COMMENTS: Under Ground  
 MAIN PANEL COMMENTS: LOCATION- Exterior of house at right side.  
 PREDOMINANT OVERLOAD PROTECTION DEVICES- Circuit breakers are provided.  
 MAIN ELECTRICAL PANEL OBSERVATIONS- White wiring used as hot legs , not properly marked in panel

SUB-PANEL COMMENTS: LOCATION- Garage  
 SUB-ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

- B. Branch Circuits - Connected Devices and Fixtures (Report as in need of repair the lack of ground fault circuit protection where required.)  
 Comments:

FEEDERS- Copper, Aluminum (220 volt OK)  
 VISIBLE BRANCH WIRING TYPE- Grounded type branch wiring present. Copper  
 BRANCH WIRING OBSERVATIONS, -  
 WIRING DEFICIENCIES- missing covers on junction boxes in attic area. Add properly.

**III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS**

- A. Heating Equipment #1:  
 Type/Energy Source: System Type- Electric Forced Air Heat Pump.  
 Comments:

Unit located at upper hall closet.  
 Heating System- The heating system operated correctly at the time of the inspection.

- B. Cooling Equipment #1:  
 Type/Energy Source: Electric.  
 Comments:

Cooling System- - Central, - Split System.  
 Trane est 2 1/2 ton 2000 unit located at exterior  
 AIR TEMPERATURE DIFFERENTIAL- Temperature drop/differential observed

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item
I	NI	NP	R					

between 15 - 20 degrees. (taken between interior return and supply air) This is considered a normal operating range.

EVAPORATOR OBSERVATIONS- debris and fungal type growth observed at interior blower, coils in need of professional cleaning/removal

CONDENSER (EXTERIOR UNIT) OBSERVATIONS- Replace insulation at refrigerant piping to unit.

- 

**C. Ducts and Vents**

*Comments:*

DUCTWORK TYPE- Fiberglass duct board and/or flexible type ducts were primarily used for distribution/return system throughout.

Ductwork, Air Chase and/or Plenum Observations- Openings observed at ducts and/or at blower unit allowing air to escape from the system. Seal all joints throughout attic.

Electrical wiring was present in the return air duct work from water heater unit installation.

**IV. PLUMBING SYSTEM**

- 

**A. Water Supply System and Fixtures**

*Comments:*

The potable water supply source is- Municipal service is primary water source.

SUPPLY PIPING TYPE- Copper, Galvanized

POTABLE WATER LINE OBSERVATIONS- Appears serviceable.

- 

**Bathroom #1 MASTER BATHROOM:**

LAVATORY- No problems observed during this inspection period.

TOILET/BIDET PLUMBING- Toilet does not flush properly.

TUB/SHOWER PLUMBING- No problems observed during this inspection period.

- 

**B. Drains, Wastes, Vents**

*Comments:*

DRAIN/WASTE & VENT PIPING TYPE- PVC plastic

SEWER PIPE OBSERVATIONS- No problems observed during this inspection period.

- 

**Bathroom #1 MASTER BATHROOM:**

LAVATORY- No problems observed during this inspection period.

TOILET/BIDET PLUMBING- No problems observed during this inspection period.

TUB/SHOWER PLUMBING- No problems observed during this inspection period.

- 

**C. Water Heating Equipment #1: (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)**

*Energy Source:*

*Comments:*

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

Electrically operated.

State 40 gallon 2001 unit located at closet.  
No problems observed during this inspection period.

- D. Hydro Therapy Equipment**  
*Comments:*  
 Not Present

**V. APPLIANCES**

- A. Dishwasher**  
*Comments:*  
 No problems observed during limited test run of appliance.

- B. Food Waste Disposer**  
*Comments:*  
**Deficiencies- Splash guard is damaged/missing.**

- C. Range Hood**  
*Comments:*  
 No problems observed during limited test run of appliance.

- D. Ranges/Ovens/Cooktops**  
*Comments:*  
 storage in unit. Unit not operated

- E. Microwave Cooking Equipment**  
*Comments:*  
 Not Present

- F. Trash Compactor**  
*Comments:*  
 Not Present

- G. Bathroom Exhaust Fans and/or Heaters**  
*Comments:*  
 Vent unit present. No problems observed during limited test run of appliance.

- H. Whole House Vacuum Systems**  
*Comments:*

I=Inspected      NI=Not Inspected      NP=Not Present      R=Not Functioning or in Need of Repair

I	NI	NP	R	Inspection Item
---	----	----	---	-----------------

Not Present

I. **Garage Door Operators**  
Comments:

Not Present

J. **Door Bell and Chimes**  
Comments:

No problems observed.

K. **Dryer Vents**  
Comments:  
Vent cap is damaged.

L. **Other Built-in Appliances**  
Comments:

Not Present

**VI. OPTIONAL SYSTEMS**

A. **Lawn Sprinklers**  
Comments:

Not Present

B. **Swimming Pools and Equipment**  
Comments:

Not Present

C. **Outbuildings**  
Comments:

Not Present

D. **Outdoor Cooking Equipment**  
Energy Source:  
Comments:

Not Present

E. **Gas Lines**  
Comments:

Not Present

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>F. Water Wells</b> (A coliform analysis is recommended.)
<i>Type of Pump:</i>				
<i>Type of Storage Equipment:</i>				
<i>Comments:</i>				
<b>Not Present</b>				

<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>G. Septic Systems</b>
<i>Comments:</i>				
<b>Not Present</b>				

<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<b>H. Security Systems</b>
<i>Comments:</i>				
security testing is not part of this inspection				

<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>I. Fire Protection Equipment</b>
<i>Comments:</i>				
<b>Not Present</b>				