

## PROPERTY INSPECTION REPORT

**Prepared For:** SAHA  
\_\_\_\_\_  
(Name of Client)

**Concerning:** 4023 San Luis San Antonio, TX 78237  
\_\_\_\_\_  
(Address or Other Identification of Inspected Property)

**By:** Jon Krauss 4255 01/29/08  
\_\_\_\_\_  
(Name and License Number of Inspector) (Date)

\_\_\_\_\_  
(Name, License Number and Signature of Sponsoring Inspector, if required)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

### ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Number: 20080141573 Phone Number: \_\_\_\_\_  
Date of Inspection: 01/29/08 Fax Number: \_\_\_\_\_  
Time of Inspection: \_\_\_\_\_  
Client Mailing Address: \_\_\_\_\_  
City/State/Zip: \_\_\_\_\_

### SPECIAL NOTES:

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

| I=Inspected |    |    |   | NI=Not Inspected | NP=Not Present | R=Not Functioning or in Need of Repair | Inspection Item |
|-------------|----|----|---|------------------|----------------|--|-----------------|
| I           | NI | NP | R |                  |                |  |                 |

**I. STRUCTURAL SYSTEMS**

**A. Foundations** (If all crawl space areas are not inspected, provide an explanation.)  
*Comments (An opinion on performance is mandatory):*

FOUNDATION TYPE- Concrete slab on grade.  
 CONCRETE FOUNDATION OBSERVATIONS- Foundation appears to be functioning normally at time of inspection.

**B. Grading and Drainage**  
*Comments*

Structure is on a slightly sloped lot. Grade at foundation appears adequate at time of inspection  
 Slight erosion noted under edge of roof around house.

**C. Roof Covering** (If the roof is inaccessible, report the method used to inspect.)  
*Comments*

METHOD USED TO INSPECT ROOF- The following was observed upon walking on the roof.  
 DESCRIPTION OF MATERIALS- Composition and/or fiberglass shingles. Note: Average life expectancy under normal installation/conditions is between 10 -14 years. Approximate age of roof. Approximate age of this roof covering is believed to be between 3 and 8 years old.

ROOF COVERING OBSERVATIONS- Seal all exposed fasteners at ridge caps, flashings on roof.  
 Starter strip around perimeter edge of roof improperly installed, not sealed down as per manufacturer installation instructions.  
 Roof covering observed showing normal wear for age.

**D. Roof Structure and Attic** (If the attic is inaccessible, report the method used to inspect.)  
*Comments*

ACCESS METHOD/LIMITATIONS- Full access  
 ATTIC OBSERVATIONS- Truss framing  
 ROOF STRUCTURE OBSERVATIONS- No problems observed during this inspection period.  
 INSULATION OBSERVATIONS- Blown type insulation (either fiberglass or rock wool) present. The insulation layer is approximately, 10 - 12 inches at most areas of attic.

Less than 6" of insulation at breakfast, at center front attic areas. Add at these areas.

**E. Walls (Interior and Exterior)**  
*Comments*

INTERIOR WALL OBSERVATIONS- INTERIOR WALLS ARE COVERED WITH

| I=Inspected |    | NI=Not Inspected |   | NP=Not Present | R=Not Functioning or in Need of Repair | Inspection Item |
|-------------|----|------------------|---|----------------|--|-----------------|
| I           | NI | NP               | R |                |  |                 |

THE FOLLOWING MATERIAL(S)- Drywall.  
 OBSERVATIONS-patching noted at rear wall master window  
 New paint noted at interior areas.

EXTERIOR WALL OBSERVATIONS-OBSERVATIONS-paint base of wood trim at corners of house.  
 Loose vinyl soffit at right center eave.

**F. Ceilings and Floors**  
*Comments*

CEILING COVERING(S)- CEILING OBSERVATIONS- No problems observed during this inspection period.

**G. Doors (Interior and Exterior)**  
*Comments*

INTERIOR DOOR OBSERVATIONS-hall closet door sticking in frame.

EXTERIOR DOOR OBSERVATIONS- Moisture related deterioration is present in door(s) and/or related trim in the following area(s). --- left exterior door . Repair damage, reseal exterior and consider cover to protect from elements.

**H. Windows**  
*Comments*

OBSERVATIONS-missing flashing at rear of house windows.  
 Swelling, water damage and signs of leakage at right bedroom, master bedroom interior of windows.

**I. Fireplace/Chimney**  
*Comments*  
 Not Present

**J. Porches, Decks and Carports (Attached)**  
*Comments*

PORCH OBSERVATIONS- No problems observed during inspection period.

**K. Other**  
*Comments*  
 Not Present

**II. ELECTRICAL SYSTEMS**

**A. Service Entrance and Panels**  
*Comments:*

| I=Inspected |    |    |   | NI=Not Inspected |  |  |  | NP=Not Present |  |  |  | R=Not Functioning or in Need of Repair |  |  |  |
|-------------|----|----|---|------------------|--|--|--|----------------|--|--|--|--|--|--|--|
| I           | NI | NP | R | Inspection Item  |  |  |  |                |  |  |  |  |  |  |  |

SERVICE COMMENTS: Under Ground  
 MAIN PANEL COMMENTS: LOCATION- Exterior of house  
 PREDOMINANT OVERLOAD PROTECTION DEVICES- Circuit breakers are provided.  
 MAIN ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

SUB-PANEL COMMENTS: LOCATION- Garage  
 SUB-ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

- B. Branch Circuits - Connected Devices and Fixtures** (Report as in need of repair the lack of ground fault circuit protection where required.):  
*Comments:*

FEEDERS- Copper, Aluminum (220 volt OK)  
 VISIBLE BRANCH WIRING TYPE- Grounded type branch wiring present. Copper  
 BRANCH WIRING OBSERVATIONS- No problems observed during this inspection period.

**III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS**

- A. Heating Equipment #1:**  
*Type/Energy Source:* System Type- Electric Forced Air Heat Pump.  
*Comments:*  
 Unit located at hall closet.  
 Heating System- The heating system operated correctly at the time of the inspection.

- B. Cooling Equipment #1:**  
*Type/Energy Source:* Electric.  
*Comments:*  
 Cooling System- - Central, - Split System.  
 Trane est 2 1/2 ton 2001 unit located at rear exterior.  
 AIR TEMPERATURE DIFFERENTIAL- Temperature drop/differential observed between 15 - 20 degrees. (taken between interior return and supply air) This is considered a normal operating range.  
 EVAPORATOR OBSERVATIONS-debris observed at blower housing in need of repairs/removal.

- C. Ducts and Vents**  
*Comments:*  
 DUCTWORK TYPE- Fiberglass duct board and/or flexible type ducts were primarily used for distribution/return system throughout.  
 Ductwork, Air Chase and/or Plenum Observations-seal all joints of ducts in attic to prevent

| I=Inspected |    | NI=Not Inspected |   | NP=Not Present  |  | R=Not Functioning or in Need of Repair |  |
|-------------|----|------------------|---|-----------------|--|--|--|
| I           | NI | NP               | R | Inspection Item |  |  |  |

air leakage.

**IV. PLUMBING SYSTEM**

**A. Water Supply System and Fixtures**  
*Comments:*

The potable water supply source is- Municipal service is primary water source.  
 SUPPLY PIPING TYPE- Copper  
 POTABLE WATER LINE OBSERVATIONS- Appears serviceable.

**Bathroom #1 HALL BATHROOM:**

LAVATORY- No problems observed during this inspection period.  
 TOILET/BIDET PLUMBING- **Water closet fill valve leaking in tank when flushed.**  
**Repair/replace valve.**  
 Loose tank from bowl in need of repairs.  
 TUB/SHOWER PLUMBING- No problems observed during this inspection period.

**Bathroom #2 MASTER BATHROOM:**

LAVATORY- No problems observed during this inspection period.  
 TOILET/BIDET PLUMBING- **Water closet fill valve leaking in tank when flushed.**  
**Repair/replace valve.**  
 Loose tank from bowl in need of repair  
 Toilet running constantly, in need of repair.  
 TUB/SHOWER PLUMBING- No problems observed during this inspection period.

**B. Drains, Wastes, Vents**  
*Comments:*

DRAIN/WASTE & VENT PIPING TYPE- PVC plastic  
 SEWER PIPE OBSERVATIONS- No problems observed during this inspection period.

**Bathroom #1 HALL BATHROOM:**

LAVATORY- No problems observed during this inspection period.  
 TOILET/BIDET PLUMBING- No problems observed during this inspection period.  
 TUB/SHOWER PLUMBING- No problems observed during this inspection period.

**Bathroom #2 MASTER BATHROOM:**

LAVATORY- No problems observed during this inspection period.  
 TOILET/BIDET PLUMBING- No problems observed during this inspection period.  
 TUB/SHOWER PLUMBING- No problems observed during this inspection period.

**C. Water Heating Equipment #1:** (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)  
*Energy Source:*  
*Comments:*

| I=Inspected |    | NI=Not Inspected |   | NP=Not Present | R=Not Functioning or in Need of Repair | Inspection Item |
|-------------|----|------------------|---|----------------|--|-----------------|
| I           | NI | NP               | R |                |  |                 |

Electrically operated.

State 40 gallon 2001 unit located at hall closet.  
No problems observed during this inspection period.

- D. Hydro Therapy Equipment**  
*Comments:*  
**Not Present**

**V. APPLIANCES**

- A. Dishwasher**  
*Comments:*  
 No problems observed during limited test run of appliance.

- B. Food Waste Disposer**  
*Comments:*  
 No problems observed during limited test run of appliance.

- C. Range Hood**  
*Comments:*  
 Unit not fully secured in place.

- D. Ranges/Ovens/Cooktops**  
*Comments:*  
 Oven present, Electric.  
 No problems observed during this inspection period.

- E. Microwave Cooking Equipment**  
*Comments:*  
**Not Present**

- F. Trash Compactor**  
*Comments:*  
**Not Present**

- G. Bathroom Exhaust Fans and/or Heaters**  
*Comments:*  
 Vent unit present. No problems observed during limited test run of appliance.

- H. Whole House Vacuum Systems**  
*Comments:*

| I=Inspected |    | NI=Not Inspected |   | NP=Not Present | R=Not Functioning or in Need of Repair | Inspection Item |
|-------------|----|------------------|---|----------------|--|-----------------|
| I           | NI | NP               | R |                |  |                 |

Not Present

I. **Garage Door Operators**  
*Comments:*

Not Present

J. **Door Bell and Chimes**  
*Comments:*

No problems observed.

K. **Dryer Vents**  
*Comments:*

No problems noted.

L. **Other Built-in Appliances**  
*Comments:*

Not Present

**VI. OPTIONAL SYSTEMS**

A. **Lawn Sprinklers**  
*Comments:*

Not Present

B. **Swimming Pools and Equipment**  
*Comments:*

Not Present

C. **Outbuildings**  
*Comments:*

Not Present

D. **Outdoor Cooking Equipment**  
*Energy Source:*  
*Comments:*

Not Present

E. **Gas Lines**  
*Comments:*

Not Present

| I=Inspected |    | NI=Not Inspected |   | NP=Not Present | R=Not Functioning or in Need of Repair | Inspection Item |
|-------------|----|------------------|---|----------------|--|-----------------|
| I           | NI | NP               | R |                |  |                 |

**F. Water Wells** (A coliform analysis is recommended.)  
*Type of Pump:*  
*Type of Storage Equipment:*  
*Comments:*  
**Not Present**

**G. Septic Systems**  
*Comments:*  
**Not Present**

**H. Security Systems**  
*Comments:*  
 security testing is not part of this inspection

**I. Fire Protection Equipment**  
*Comments:*  
**Not Present**