

PROPERTY INSPECTION REPORT

Prepared For: SAHA

(Name of Client)

Concerning: 623 Matthews San Antonio, TX 78237

(Address or Other Identification of Inspected Property)

By: Jon Krauss 4255 02/15/08

(Name and License Number of Inspector) (Date)

(Name, License Number and Signature of Sponsoring Inspector, if required)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC).

The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report Number: 20080241840 Phone Number: _____
Date of Inspection: 02/15/08 Fax Number: _____
Time of Inspection: _____
Client Mailing Address: _____
City/State/Zip: _____

SPECIAL NOTES:

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair
I	NI	NP	R	Inspection Item	

I. STRUCTURAL SYSTEMS

- A. Foundations** (If all crawl space areas are not inspected, provide an explanation.)
Comments (An opinion on performance is mandatory):

FOUNDATION TYPE- Concrete slab on grade.
 CONCRETE FOUNDATION OBSERVATIONS- Foundation appears to be functioning normally at time of inspection.
 Minor signs of past settlement observed in the form of hair line type cracking to finished surfaces. Smaller, fracture cracks to finished floor in garage observed.

- B. Grading and Drainage**
Comments

Structure is on a slightly sloped lot. Grade at foundation appears adequate at time of inspection.

- C. Roof Covering** (If the roof is inaccessible, report the method used to inspect.)
Comments

METHOD USED TO INSPECT ROOF- The following was observed upon walking on the roof.
 DESCRIPTION OF MATERIALS- Composition and/or fiberglass shingles. Note: Average life expectancy under normal installation/conditions is between 10 -14 years.
 ROOF COVERING OBSERVATIONS-damaged shingles 4 to 7 at left side slope near edge of roof
 Seal all exposed fasteners at ridge caps, flashings on roof.
 Starter strip around perimeter edge of roof improperly installed, not sealed down.
 GUTTERING OBSERVATIONS- DAMAGE/DEFECTS NOTED- Gutter is sloped improperly and holding water

- D. Roof Structure and Attic** (If the attic is inaccessible, report the method used to inspect.)
Comments

ACCESS METHOD/LIMITATIONS- Full access
 ATTIC OBSERVATIONS- Truss framing
 ROOF STRUCTURE OBSERVATIONS- Add blocking at gaps on hip to ridge trusses at front attic, at rear attic areas.
 INSULATION OBSERVATIONS- Blown type insulation (either fiberglass or rock wool) present. The insulation layer is approximately, 8 to 10 inches thick.

- E. Walls (Interior and Exterior)**
Comments

INTERIOR WALL OBSERVATIONS- INTERIOR WALLS ARE COVERED WITH

I=Inspected				NI=Not Inspected	NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R				

THE FOLLOWING MATERIAL(S)- Drywall.

EXTERIOR WALL OBSERVATIONS- EXTERIOR WALLS ARE CONSTRUCTED OF THE FOLLOWING MATERIALS-

Aluminum/vinyl siding. Soffit(s), eave(s), and/or trim are painted wood. Cement Fiber type siding.

OBSERVATIONS-paint, seal base of wood trim at corners, around house.

-

F. Ceilings and Floors
Comments

CEILING COVERING(S)- CEILING OBSERVATIONS- No problems observed during this inspection period.

-

G. Doors (Interior and Exterior)
Comments

INTERIOR DOOR OBSERVATIONS- No problems observed during this inspection period.

EXTERIOR DOOR OBSERVATIONS- Moisture related deterioration is present in door(s) and/or related trim in the following area(s). ---breakfast exterior door . Repair damage, reseal exterior and consider cover to protect from elements.

-

H. Windows
Comments

OBSERVATIONS-swelling, water damage observed at windows at right bedrooms, at rear bedroom

Missing screens at right bedroom, at rear bedroom, at master.

Torn/damaged screen at living room window

-

I. Fireplace/Chimney
Comments

Not Present

-

J. Porches, Decks and Carports (Attached)
Comments

PORCH OBSERVATIONS- No problems observed during inspection period.

-

K. Other
Comments

Not Present

II. ELECTRICAL SYSTEMS

-

A. Service Entrance and Panels
Comments:

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair
I	NI	NP	R	Inspection Item	

SERVICE COMMENTS: Under Ground
 MAIN PANEL COMMENTS: LOCATION- Exterior of house
 PREDOMINANT OVERLOAD PROTECTION DEVICES- Circuit breakers are provided.
 MAIN ELECTRICAL PANEL OBSERVATIONS- white wires used as hot legs in panel but not properly marked as hot legs.

SUB-PANEL COMMENTS: LOCATION- Garage
 SUB-ELECTRICAL PANEL OBSERVATIONS- No problem(s) noted at the time of inspection.

- B. Branch Circuits - Connected Devices and Fixtures** (Report as in need of repair the lack of ground fault circuit protection where required.):
Comments:
 FEEDERS- Copper, Aluminum (220 volt OK)
 VISIBLE BRANCH WIRING TYPE- Grounded type branch wiring present. Copper
 BRANCH WIRING OBSERVATIONS- No problems observed during this inspection period.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

- A. Heating Equipment #1:**
Type/Energy Source: System Type- Electric Forced Air Heat Pump.
Comments:
 Unit is located in, closet
 Heating System- The heating system did not operate in emergency heat setting at time of inspection

- B. Cooling Equipment #1:**
Type/Energy Source: Electric.
Comments:
 Est. Size: 2 1/2 ton
 Cooling System- - Central, - Split System.
 AIR TEMPERATURE DIFFERENTIAL- Temperature drop/differential observed between 15 - 20 degrees. (taken between interior return and supply air) This is considered a normal operating range.
 EVAPORATOR OBSERVATIONS- debris observed at interior blower housing in need of proper removal.

- C. Ducts and Vents**
Comments:

I=Inspected				NI=Not Inspected				NP=Not Present				R=Not Functioning or in Need of Repair			
I	NI	NP	R	I	NI	NP	R	I	NI	NP	R	I	NI	NP	R

DUCTWORK TYPE- Fiberglass duct board and/or flexible type ducts were primarily used for distribution/return system throughout.
 Ductwork, Air Chase and/or Plenum Observations-seal all duct connections throughout attic

IV. PLUMBING SYSTEM

A. Water Supply System and Fixtures
Comments:

The potable water supply source is- Municipal service is primary water source.
 SUPPLY PIPING TYPE- Copper
 POTABLE WATER LINE OBSERVATIONS- Appears serviceable.

Bathroom #1 MASTER BATHROOM:

No access to master bath at time of inspection

Bathroom #2 HALL BATHROOM:

LAVATORY- No problems observed during this inspection period.
 TOILET PLUMBING- Water closet fill valve leaking in tank when flushed. Repair/replace valve.
 Tank loose from bowl, in need of repairs
 TUB/SHOWER PLUMBING- missing stopper at tub.
 Water damage on wall outside of tub from splash

B. Drains, Wastes, Vents
Comments:

DRAIN/WASTE & VENT PIPING TYPE- PVC plastic
 SEWER PIPE OBSERVATIONS- No problems observed during this inspection period.

Bathroom #1 MASTER BATHROOM:

Bathroom #2 HALL BATHROOM:

C. Water Heating Equipment #1: (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)

Energy Source: Electrically operated.
Comments:

Location/Coverage: Closet, Hallway.

State 40 gallon 2000 unit;

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

No problems observed during this inspection period.

- | | | | | |
|--------------------------|--------------------------|-------------------------------------|--------------------------|-----------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | D. Hydro Therapy Equipment |
| <i>Comments:</i> | | | | |
| Not Present | | | | |

V. APPLIANCES

- | | | | | |
|---|--------------------------|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | A. Dishwasher |
| <i>Comments:</i> | | | | |
| Discharge hose is, installed without an air gap. The drain line should be raised to the underside of the counter top. | | | | |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | B. Food Waste Disposer |
| <i>Comments:</i> | | | | |
| No problems observed during limited test run of appliance. | | | | |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | C. Range Hood |
| <i>Comments:</i> | | | | |
| No problems observed during limited test run of appliance. | | | | |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | D. Ranges/Ovens/Cooktops |
| <i>Comments:</i> | | | | |
| Oven present, Electric. No problems observed during this inspection period with operation of unit | | | | |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | E. Microwave Cooking Equipment |
| <i>Comments:</i> | | | | |
| Not Present | | | | |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | F. Trash Compactor |
| <i>Comments:</i> | | | | |
| Not Present | | | | |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | G. Bathroom Exhaust Fans and/or Heaters |
| <i>Comments:</i> | | | | |
| Vent unit present. No problems observed during limited test run of appliance.
No access to master bath | | | | |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | H. Whole House Vacuum Systems |
| <i>Comments:</i> | | | | |
| Not Present | | | | |

I=Inspected		NI=Not Inspected		NP=Not Present	R=Not Functioning or in Need of Repair	Inspection Item
I	NI	NP	R			

I. **Garage Door Operators**
Comments:

Not Present

J. **Door Bell and Chimes**
Comments:

No problems observed.

K. **Dryer Vents**
Comments:

No problems noted.

L. **Other Built-in Appliances**
Comments:

Not Present

VI. OPTIONAL SYSTEMS

A. **Lawn Sprinklers**
Comments:

Not Present

B. **Swimming Pools and Equipment**
Comments:

Not Present

C. **Outbuildings**
Comments:

Not Present

D. **Outdoor Cooking Equipment**
Energy Source:
Comments:

Not Present

E. **Gas Lines**
Comments:

Not Present

I=Inspected		NI=Not Inspected		NP=Not Present		R=Not Functioning or in Need of Repair		Inspection Item	
I	NI	NP	R						
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	F.	Water Wells (A coliform analysis is recommended.) <i>Type of Pump:</i> <i>Type of Storage Equipment:</i> <i>Comments:</i> Not Present				
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	G.	Septic Systems <i>Comments:</i> Not Present				
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	H.	Security Systems <i>Comments:</i> security testing is not part of this inspection				
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	I.	Fire Protection Equipment <i>Comments:</i> Not Present				