



818 S. FLORES ST. SAN ANTONIO, TEXAS 78204 www.saha.org

Procurement Department

ADDENDUM #2

To: 1005-909-62-3192
RFQ for Repairs at 547 E. Villaret
Date: June 10, 2010

Question: Has this home been lead paint renovated or tested by a certified EPA company since it was built in 1970?

Answer: Yes

Contractor shall supply all materials needed for this project.

The mini-blinds listed in the attachment under “Miscellaneous Repair Work” shall be supplied by the Contractor.

Did read:

Install (6) mini blinds to be provided by HD
Install (1) vertical blind to be provided by HD

Should read:

Install (6) mini blinds to be provided by Contractor
Install (1) vertical blind to be provided by Contractor

By: Carl Bottoms
Procurement Supervisor

Date: June 10, 2010