



818 S. FLORES ST. ① SAN ANTONIO, TEXAS 78204 ① www.saha.org

Procurement Department

ADDENDUM #2

To: RFQ # 1111-926-78-3670
For: Mold Remediation at 1818 Krockner Way
Date: January 6, 2012

Question 1.: What kind of assessment was performed on the property (i.e. spore count or air quality).

Answer 1: A Visual mold assessment.

By: *Carl Bottoms*
Procurement Supervisor

Date: January 6, 2012