



Photo 1: Kitchen- Clean exterior window.



Photo 2: Kitchen- Clean exterior window.





Photo 3: Kitchen- Clean shelf below sink.




Photo 4: Front- Removed caulk joint on the exterior window.





Photo 5: Front- Removed caulk joint on the exterior window.



Photo 6: Front- Inspection hole below the left side of the exterior window.





Photo 7: Hall Bath Room- Wall cavity behind toilet at head end of tub.



Photo 8: Bedroom #3- Removed caulk along exterior wall window.





Photo 9: Master Bed Room- Removed caulk along exterior wall window.



Photo 10: Master Bed Room- Inspection hole below the right side of the exterior wall window.





Photo 11: Master Bed Room- Removed window sill and apron along the side exterior wall window.



Photo 12: Master Bath Room- Remove caulk at the top lip of the fiberglass tub surround.





Photo 13: Master Bath Room- Wall cavity at the head end of the tub.



Photo 14: HVAC Closet- Return air plenum.





Photo 15: HVAC Closet- Return air plenum side of AC condensate coil.

